

FORCE 5650 Maintenance Overview

rev date: Feb 2022

	Hours of Operation											
	Each Use	20	40	60	80	100	200	300	400	500	1000	
HONDA V-TWIN												
check oil	Y											
change oil		Y				Y	Y	Y	Y	Y	Y	
change oil filter		Y				Y	Y	Y	Y	Y	Y	
clean air filter	Y		Y			Y	Y	Y	Y	Y	Y	
intake air system	ensure clean & no obstructions											
Howden / Roots BLOWER see owner's manual p17 AEON PD Synthetic Lubricant change every 6,000 hours			check level			check level	check level	check level	check level	check level	check level	check level
intake air system	ensure clean & no obstructions											
Other												
grease zirc fittings						Y	Y	Y	Y	Y	Y	Y

INTEC CONTACTS TO ASSIST

Patrick Turner – Technical Service
office: 303-833-6644 ext: 111
email: patrickt@inteccorp.com

Jason Brown – Technical Service
office: 303-833-6644 ext: 105
email: jasonb@inteccorp.com

Wishing you many profit generating opportunities thru the use of your FORCE 5650. Thank you for your support of Intec!

Ray Lavallee

President, Insulation Technology Corporation
mobile: 303-653-1257
email: rayl@inteccorp.com